

State Route (SR) / US Route or Road Name and Description:

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

Are corrective actions required by this inspection report (Y/N):

DATE: 6-6-//

Page 1 of 6

p		*		K.			
	Wolf River Blvd.						
County(ies):	TDOT PIN:	NPDES Permit (NOC)	NPDES Permit (NOC) #:		Number of Recurring	Number of New	Number of Un-Corrected
Shelby	101615	TNR153299)	Corrective Actions:	Corrective Actions:	Sediment Releases:	Sediment Releases:
TDOT Construction No.: 7994-1535-54	TDOT Contract No.:	Contractor: Acuff Enterprises Inc.		6	2	0	0
I certify, under penalty of law prepared under my direction designed to assure that quali information presented. Base manage the system, or those information, I cerify that inspersion and sediment contabove. I certify that erosion identified outfall where install recorded in the table above, submitting false information, knowing violations.	or supervision in accordance ified personnel properly gated on my inquiry of the person directly responsible ctions of storm water dischards have been performed and sediment controls in the led as planned and designed am aware that there are s	the with a system thered and evaluated to or persons who the for gathering the the large points (outfalls) and the lable the drainage area of the d in working order as tignificant penalties for	Contracto	Gerald "Jerry" S r EPSC Inspector and T Tom Acufo pject Supevisor / Design /pe): Michael Reb	Stanfill Title (print or type): f nee and Title	Signature: Signature: Signature: Signature:	tanfil acuff

TDOT EPSC Inspection Weekly Rainfall Data Log

		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date	Day of Week		Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or YES
Date	Day of Week	(%)	(in)	(in)	(in)	(in)	(in)	(in)		If No, explain and initial:
	Sunday		*****		N/A	N/A	N/A	N/A		,
5/6/11	Monday	10	Ö	0	N/A	N/A	N/A	N/A		In process of correcting
	Tuesday	10			N/A	N/A	N/A	N/A		1
	Wednesday	30			N/A	N/A	N/A	N/A		actions.
12/11	Thursday	10			N/A	N/A	N/A	N/A		
/3/11	Friday	0	0	0	N/A	N/A	N/A	N/A		
13/11	Saturday	0			N/A	N/A	N/A	N/A	•	
6/5/11	Sunday	0			N/A	N/A	N/A	N/A		
, ,	Monday				N/A	N/A	N/A	N/A		
										(Additional pages may be attached, if needed)

					(Additional pages may
Predicted Precipitation	Source:	www.wea	ather.com		

	OF THE STA
6	AGRICUITURE
EA.	AGRICULTURE
1/2	1796

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	6/6/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	6/3/2011		22	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	6/6/2011	T=3-25-11	16,33,35		Area needs to be stable. See photo
1B	1	22+00	RT	6/6/2011	T=3-25-11	16,24,33,35	Î.	Area needs to be stable. See photo
1C	1	21+00	LT	6/6/2011	T=3-25-11	10,12,16,33,35	I	Area needs to be stable. See photo
2A	1	33+50	RT	3/25/2011	T=3-25-11	16,33	FM	The damaged SFB will need to be repaired before work begins.
2B	1	35+50	RT	3/25/2011	T=3-25-11	16,33	S	STABLE (NO ACTION NEEDED)
3	1	34+50	LT				S	The area has not been disturbed.
4	1	40+00	RT	1. 1.00.01			S	The area has not been disturbed.
5A	1	49+00	RT				S	The area has not been disturbed.
5B	1	50+00	RT				S	The area has not been disturbed.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15		29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

CONDITION CODES

	SF T	HE.		
A	GRIC	UT M	URE	
	(8)	MER 96	33	<i>y</i>

State/US		

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	6/6/2011	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				S	The area has not been disturbed.
6	1	56+00	LT				S	The area has not been disturbed.
7	1	60+00	RT		997		S	The area has not been disturbed.
8A	1	73+00	RT				S	The area has not been disturbed.
8B	2	75+50	RT				S	The area has not been disturbed.
8C	1	71+00	LT				S	The area has not been disturbed.
8D	2	75+50	LT				S	The area has not been disturbed.
8E	1	71+50	LT			35.500	S	The area has not been disturbed.
9A	2	80+00	RT	6/6/2011	T=5-31-11	16,35	S	Stable (No action needed)
9B	2	80+00	LT	6/6/2011	T=5-31-11	16	S	Wattles need to be installed. See Photo

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Temporary Diversion Berm or Ditch 16 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 2 Temporary Mulch R 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 33 С Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 20 34 **Enhanced Silt Fence** 6 Riprap Outlet Structure Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO 8 Repeat Occurrence 37 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, reprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Haul Road Other (O#2): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 Other (O#3):

CONDITION CODES

State/US Route	or Road Name:
----------------	---------------

۸	In	lf	River	Rlvd	
•	v		IVIVEI	DIVU.	

-3537-54	

TDOT Construction No.: 79954-3537-54 TDOT Contract No.:


Date	6/6/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	6/6/2011	T=5-31-11	16	S	STABLE (NO ACTION NEEDED)
10A	2	85+00	RT	6/6/2011	T=5-31-11	16,24	s	Monitoring BMP's.
10B	2	85+00	RT	6/6/2011	T=5-31-11	16,24,35	S	Monitoring BMP's.
10C	2	85+50	LT	6/6/2011	T=5-31-11	16,35	S	STABLE (NO ACTION NEEDED)
10D	2	84+50	LT	6/6/2011	T=5-31-11	16,35	S	STABLE (NO ACTION NEEDED)
11A	2	92+50	RT	6/6/2011	T=5-31-11	16,24,35	FM	Wattles need to be installed. See Photo
11B	2	92+50	LT	6/6/2011	T=5-31-11	10.16,35	S	Monitoring BMP's.
11C	2	92+00	LT	6/6/2011	T=5-31-11	16,35	FM	STABLE (NO ACTION NEEDED)
	1	11+28	LT	6/3/2011	T=6-3-11	19,35	S	STABLE (NO ACTION NEEDED)
	1	13+40	RT	6/6/2011		23,29,30	М	Make corrections to construction exit to function properly and to contorl <u>DUST</u> . See photo
	1	107+75	CL	6/3/2011		23,29,30	I,C	Make corrections to construction exit to function properly and to control <u>DUST</u> . See photo

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	emporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	Ï	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

CONDITION CODES






City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Sta. 107+75 CL Dress and stabilize construction exit to function properly and to control \overline{DUST} . (I,C)



Eastbound WRB from Sta. 107+75 CL Dress and stabilize construction exit to function properly and to control <u>DUST</u>. (I,C)



Southbound Farmington Blvd. from Sta. 107+75 CL Dress and stabilize construction exit to function properly and to control <u>DUST</u>. (I,C)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138